

## Overspray and Fallout Clay - Light and Straight

For the removal of overspray and other contaminates such as industrial fallout, jet fuel residue, tar and other general airborne pollution from painwork in preperation for polishing or waxing.



## **Additional Information**

- Clay bar. Removes overspray & other contaminates prior to polishing or waxing.
- · Works on any painted surfaces, glass, chrome & plastic.
- · Will not damage or mark the paintwork.
- For best results use with a little soap & water from a spray bottle.
- Also available for Dark & Metallic paint, please see Power-TEC Part No. Part Number 91455.

http://powertec.co.uk/product/91454



